

93-B-5306 Comments

6.1.94

Deputy, AC/S requested ^{cursor} review of aforementioned contract and comments are:

1) drawings are 60% vice 90% ^{Right} (see 93-B-5306, PWD, May 13). Appears PWD provided wrong drawings if no changes between 60 and 90% then no problem, but if changes were made, EMD is reviewing wrong submittal.

2) IR Records show that the following wells were contaminated and are being closed ✓ via this contract: HP-602, 634, 645, 651, 653, 660

~~HP-606, 610, 637, 652~~ ^{Right}
Attention! HP-606, ~~610~~, ~~637~~, ~~652~~ and AS-106, 4150 were contaminated as well but are not being closed by 93-B-5306. Correct, not on this contract

IR Records also show that following wells ^{Project broken in several} chunks: were not operating due to production failure: HP-639, 649, 655 and TC-329, 504, 901. These wells are not being closed by 93-B-5306.

: contaminated but resampled clean

: closed via 91-B-7605

○ : being added

Handwritten signature

CLW

0000002356