

03.01-4/11/2000-02427



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 4
SAM NUNN ATLANTA FEDERAL CENTER
61 FORSYTH STREET, S.W.
ATLANTA, GEORGIA 30303

April 11, 2000

4WD-FFB

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Ms. Katherine Landman
Department of the Navy - Atlantic Division
Naval Facilities Engineering Command
Code 1823
Norfolk, Virginia 23511-6287

SUBJ: MCB Camp Lejeune
Draft Supplemental Groundwater Investigation
Operable Unit No.17-Sites 90, 91 & 92

Dear Ms. Landman:

The Environmental Protection Agency has completed its review of the above subject document. The Agency agrees with the stated conclusions. Comments are enclosed.

If you have any questions or comments, please call me at
(404) 562-8538

Sincerely,

A handwritten signature in black ink, appearing to read "Gena D. Townsend".

Gena D. Townsend
Senior Project Manager

Enclosure

cc: David Lown, NCDEHNR
Rick Raines, MCB Camp Lejeune

COMMENTS

1. Page 1-1, 1st paragraph, 2nd to last sentence: incomplete sentence.
2. Add the groundwater direction flow to the figures.
3. Site 90, MW04: The detection of trichloroethene in MW04, although at low levels, would require further delineation, due to the close proximity of a dry cleaner operation and the lack of groundwater data in this area.
4. Site 91, MW16: In 1997 sampling results from this well only detected Bis(2-ethylhexyl)phthalate. In 1999 sampling results identified dichlorobenzenes and trichlorobenze. Although the levels are below regulatory limits, there were not detected in 1997. Is there an explanation for this occurrence, (i.e., bad sample, lab error, etc..)? This well should be re-sampled.