

WELL PU

JANUARY

FEBRUARY

MARCH

APRIL

MAY

JUNE

1980
Madison Point

WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS			
601							Out →															
602	44'	60'	16'	33'	60'	27'	35'	58'	23'	35'	60'	25'	38'	60'	22'	45'	12'	33'				
603				No Airline →																		
606	30'			30'			35'	50'	15'	30'	51'	21'	30'	51'	21'	30'	51'	21'				
608	40'	59'	19'	39'	53'	14'	40'	49'	9'	38'	49'	11'	40'	51'	11'	38'						
609	29'				51'		51'	29'	22'	29'	54'	25'	31'	46'	15'	30'	46'	16'	A/L 60'			
610							Out													A/L 63		
611							Cased →															
612	20'	42'	22'				34'	45'	11'	37'	53'	16'	40'	54'	14'							
613							Out													Out →		
614							Cased →															
615	24'	38'	14'	25'			26'	37'	11'	26'	35'	7'	24'	38'	14'				CLW			

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

000003641

WELL PU

JANUARY

FEBRUARY

MARCH

APRIL

MAY

JUNE

WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS
616		10'			10'		35'	10'	25'	35'	10'	25'	35'	10'	25'	35'	10'	25'	
620		AIR LINE BROKEN																	
621					Caved														
626	40'				49'			51'		50'	40'	10'		38'			29'		
627					Caved														
632	24'						40'	^{more} out		out						23'			
633	32'	18'	14'		25'		38'	18'	20'	38'	25'	13'	38'	25'	13'	38'	25'	8'	
634	20'	23'	3'	20'	50'	30'	20'	50'	30'	20'	50'	30'	20'	50'	30'				
635				50'	38'	12'	50'	38'	12'	38'	50'	12'	50'	38'	12'				
636	30'	58'	28'				30'	58'	28'	30'	20'	10'	30'	58'	28'				
637	65'	95'	30'		100'		60'	78'	12'	60'	75'	15'	78'	70'	8'			45'	
638					out														
							70'	out											CLW →

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

000003642

WELL PU

JANUARY

FEBRUARY

MARCH

APRIL

MAY

JUNE

1980

WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS
639							75'	55'	20'	51'	78'	27'		66'			66'		
640				20'			20'	45'	25'	26'	45'	19'	20'	46'	20'	20'	40'	20'	
641	45'	81'	36'	41'	75'	34'	Note out			45'	78'	33'	48'	72'	24'				
642					85'		50'	87'	37'	50'	86'	36'	30'	75'	45'				
651	25'	100'	75'	25'	102'	77'	75'	110'	85'	27'	97'	70'	27'	96'	69'	30'			
652	92'	95'	3'	93'	98'	5'	93'	100'	7'	91'	100'	9'	90'	98'	8'	95'	98'	3'	
653	30'	79'	49'	30'	72'	42'	38'	70'	32'	35'	72'	37'	37'	70'	33'	34'			
654	32'	58'	26'	31'	80'	49'				34'	60'	22'	32'	60'	28'				
M-1							out			out		→							
M-2	29'	10'	29'	39'	10'		45'	71'	26'	39'	10'	29'	39'	10'	29'	39'	10'	29'	

CLW

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

0000003643