

<u>JANUARY</u>				<u>FEBRUARY</u>			<u>MARCH</u>			<u>APRIL</u>			<u>MAY</u>			<u>JUNE</u>			REMARKS
WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	
MCAS-110																			
TC B 100	21'	40'	19'	20'	29'	9'	20'	33'	7'	20'	28'	8'	21'	36'	15'				
H 201																			Air Line out
D 502																			Air Line out
J 504					30'		20'			23'	45'	22'	24'						
E 600	35'	36'	1'	38'	32'	6'	38'	31'	7'		38'		38'	30'	8'				
K 604	30'	10'	20'	26'	22'	4'	40'	20'	20'	40'	19'	21'	38'	15'	23'				
F 700	40'	15'	25'	40'	25'	15'	40'	30'	10'	38'	35'	3'	40'	30'	10'				
G 901																			Gone Cover
L 1000	24'	30'	6'	20'	30'	10'	20'	36'	16'	21'	38'	17'	22'	27'	7'				
M 1001	10'	22'	12'	45'	42'	3'	28'	43'	15'	27'	44'	17'	31'	54'	23'				
																			CLW
																			0000004007

JANUARY				FEBRUARY			MARCH			APRIL			MAY			JUNE			REMARKS
WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	
MCAS-110																			
MCAS																			
106	26'	31'	5'	26'	32'	6'	25'	30'	5'	28'	32'	4'	29'	18'	42'				
<sup>5</sup> 131	26'	30'	4'	28'	34'	6'	28'	32'	4'	31	35	4'	29'	33'	4'				
<sup>5</sup> 190	46'	52'	6'	43'	48'	5'	44'	48'	4'	43'	48'	5'	35'	50'	15'				
<sup>7</sup> 191	42'	48'	6'	44'	50'	6'	40'	47'	7'	43'	49'	6'	43'	60'	17'				
203	28'	31'	3'	26'	28'	2'	27'	33'	6'	27'	30'	3'	34'	25'	9'				
<sup>R</sup> 1251	25'	46'	21'	21'	25'	4'	24'	27'	3'	21'	28'	7'	25'						
<sup>8</sup> 1253										36'	38'	2'	40'						
<sup>P</sup> 1254	23'	28'	5'	22'	25'	3'	21'	27'	6'	10'	24'	14'	24'	40'	16'				
<sup>O</sup> 1255	14'	44'	30'	10'	34'	24'	14'	31'	17'	8'	34'	26'	8'	50'	42'				CLW
<sup>N</sup> 1256	21'	48'	27'	14'	41'	27'	17'	50'	33'	18'	37'	19'	19'	45'	26'	00	00	00	4008

STAT = STATIC

PUMP LEV. = PUMPING LEVEL

JANUARY

FEBRUARY

MARCH

WELL PU

APRIL

MAY

JUNE

MCAS-110

WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS
4140	31'	36'	5'	32'	37'	5'	32'	38'	6'	30'	37'	7'	40'	35'	5'				
4150	29'	32'	3'	31'	35'	4'	28'	31'	3'	30'	33'	3'	45'	35'	10'				
5001		40'		35'	42'	7'	34'	39'	5'	35'	39'	4'	30'	65'	15'				
5009	34'	39'	5'	35'	41'	6'	33'	38'	5'	33'	39'	6'	20'	60'	40'				

CLW

0000004009

STAT. = STATING PUMP LEV. = PUMPING LEVEL

CLW

0000004010

July  
JANUARYAugust  
FEBRUARYSept  
MARCH

WELL

PIE

OCT.  
APRILNov  
MAYDec  
JUNE

MCAS-110

WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS
TC <sub>B</sub> 100	20'	37'	17'	20'	41'	21'	20'	35'	15'	20'	30'	10'	20'	36'	16'	20'	35'	15'	
H 201	20'	35'	15'	20'	45'	25'	47'	34'	13'	45'	36'	9'	49'	25'	24'	50'	25'	25'	
P 502		25'		22'	26'	4'	22'	21'	1'	20'	22'	2'	20'	18'	2'	20'	22'	2'	
J 504	22'	53'	31'	22'	59'	35'	20'	57'	37'	20'	55'	35'	21'	58'	37'	20'	55'	35'	
B 600	13'	23'	10'	20'	25'	5'	15'	23'	8'	21'	15'	9'	15'	20'	5'	15'	15'	0'	
K 604	19'	40'	21'	20'	40'	20'	20'	39'	19'	22'	38'	16'	21'	38'	17'	22'	38'	16'	
F 700	36'	46'	10'	24'	49'	21'	36'	54'	18'	26'	51'	25'	35'	48'	13'	36'	45'	9'	
G 901																			
L 1000	22'	26'	4'	20'	45'	25'	22'	30'	8'	20'	23'	3'	20'	24'	4'	20'	22'	2'	
A 1001	30'	35'	5'	29'	50'	21'	31'	49'	18'	30'	45'	15'	30'	50'	20'	30'	45'	15'	
TC <sub>D</sub> 325										20'	41'	21'	40'			40'			

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

CLW

000004011

~~JANUARY~~ July  
MCAS-110

~~FEBRUARY~~ August

~~MARCH~~ Sept.

~~APRIL~~ Oct.

~~MAY~~ Nov

~~JUNE~~ Dec.

WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS
AS <sub>u</sub> 106		30'		30'	22'	8'	40'	39'	1'	45'	40'	5'	35'	60'	25'	18'	13'	5'	9
S 131	30'			30'	30'	0	30'	31'	1'	30'	33'	3'	28'						1-7-83 Pit level note Book
S 190		48'		35'	50'	15'	35'	49'	14'	35'	43'	8'	35'	48'	13'	35'	45'	10'	
T 191	34'			45'	50'	5'	45'	46'	1'	43'	48'	5'	50'	45'	5'	34'	54'	20'	
203		28'		33'	32'		34'	35'	1'	25'	25'	1'	25'	35'	10'	25'	35'	10'	
R 1251	10'	39'	29'	25'	25'	0	21'	25'	4'	20'	21'	1'	20'	24'	4'	18'	25'	7'	
R 1253	39'	40'	1'	40'	40'	0	41'	40'	1'	34'	40'	6'	38'	40'	2'	39'	40'	1'	
P 1254	24'	33'	9'	25'	32'	7'	35'	25'	10'	22'	26'	4'	24'	25'	1'	24'	30'	6'	
V 1255				11'	45'	34'	11'	40'	29'	10'	35'	25'	10'	45'	35'	15'	40'	25'	
N 1256	20'	52'	32'	20'	52'	32'	25'	50'	25'	18'	50'	32'	18'	45'	27'	20'	45'	25'	
414		35'		32'	35'	3'	34'	45'	11'	29'	34'	5'	30'	35'	5'	30'	45'	15'	
4150	32'	38'	6'	30'	37'	7'	31'	39'	8'	30'	35'	5'	30'	35'	5'	30'	38'	8'	

STAT. = STATIC

PUMP LEV. = PUMPING LEVEL

JANUARY  
July

FEBRUARY  
Aug.

MARCH  
Sept.

WELL PIE

APRIL  
Oct.

MAY  
Nov.

JUNE  
Dec.

MCAS-110

WELL #	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	STAT.	PUMP LEV.	DRAW DOWN	REMARKS
5001	40'	60'	20'	36'	40'	4'	20'	46'	26'	20'	35'	15'	18'	35'	17'	18'	35'	17'	
5009		60'		30'	55'	25'	11'	37'	26'	-	47'	-	26'	35'	5'	10'	43'	33'	

CLW

0000004012