



DEPARTMENT OF THE NAVY
NAVAL HOSPITAL
CAMP LEJEUNE, N.C. 28542

6240
37
IN REPLY REFER TO

15 Jan 85

From: Commanding Officer

To:

Base Maintenance Officer, Marine Corps Base, Camp Lejeune, NC 28542


Subj: ENVIRONMENTAL HEALTH INSPECTION RESULTS

Ref: (a) NAVMED P-5010
(b) Base Order 6240.7

Encl: (1) Sanitation Inspection Report

1. In accordance with reference (a), an Environmental Health Inspection was performed by the Occupational and Preventive Medicine Department. Enclosure (1) notes the facility, time and date of inspection and is submitted for your information and/or appropriate action.

2. If any additional information is required, please call the Surveillance Section of Occupational and Preventive Medicine Department at extension 5707 or 2707.


M. P. CENTRY
By direction

Copy to:

Water Quality Control Lab

CLW
0000004510

ENVIRONMENTAL HEALTH/SANITATION INSPECTION REPORT

NAV HOSP (CLNC) 6240/1A (8-83)

FROM: **Commanding Officer, Naval Hospital, Camp Lejeune, NC 28542**
 TO: **Base Maintenance Officer, Marine Corps Base, Camp Lejeune, NC 28542**

REF: (a) NAVMED P-5010


In accordance with reference (a) an environmental health/sanitation inspection of WATER TX. PLANT TT 38 was conducted on 11 JANES by M.T. STASH Amz. Findings and recommended corrective action are as follows.

AN * INDICATES THAT THE FINDING HAS BEEN PREVIOUSLY REPORTED.

FINDINGS	RECOMMENDED CORRECTIVE ACTION
<p>STOVE AND COFFEE MESS LOCATED IN H₂O ANALYSIS LAB.</p> <p>NO PROTECTIVE GEAR (GLOVES & APRON) USED IN H₂O ANALYSIS LAB.</p> <p>RESPIRATOR LOCATED IN H₂O ANALYSIS LAB ACROSS FROM CL₂ ROOM WITHIN IN THE FLOW OF AIR. (IF LEAK WAS DETECTED, RESPIRATOR WOULD BE IN ACCURABLE.) NO EFFECTIVE RESPIRATOR PROTECTION TRAINING BEING DOCUMENTED OR DONE.</p> <p>50 LB LIME BAGS BEING STORED BY CL₂ INJECTION SITE AND A SMALL CHAIN IS UTILIZED TO HOLD CL₂ TANKS (THIS CAN BE A HAZARD IF A BAG OF LIME WAS TO FAIL AND HIT THE CL₂ TANKS.)</p> <p>OPERATOR NOT USING PROTECTIVE GEAR WHEN MANUALLY INJECTING LIME INTO H₂O SYSTEM.</p> <p>NO EYE WASH FACILITY NOTED.</p> <p>AMMONIA BEING STORED IN ROOM NEXT TO CL₂ TANKS (SHOULD BE STORED OUTSIDE OF ROOM FOR CL₂ DETECTION.)</p>	<p style="text-align: right;">CLW 000000451#</p>

2. The overall sanitary condition was found to be: Good

Copy to:
Water Quality Control Lab

APPROVED: 
M. P. GENTRY
 By direction